

RECALL OF CERTAIN KTM 50 SX MODELS

KTM recalls certain 50 SX models of model year 2017 to the workshops of authorized KTM dealers in order to replace the chain connecting link.

Internal KTM quality checks have established that a defective chain connecting link was installed in a small number of KTM 50 SX models due to deviations in manufacturing at a supplier. This can lead to premature failure of the chain connecting link and possible consequential damage. Therefore, the link must be replaced on all affected motorcycles.

Customers of affected and already distributed motorcycles are informed by a personal letter and are asked to immediately contact an authorized [KTM dealer](#) to arrange an appointment. In addition, customers can check online in the "[Service](#)" area on the KTM website if their motorcycle is affected by the recall.

The replacement of the chain connecting link can be carried out by authorized KTM dealers only. This check is a guarantee that is completely free of charge.

www.ktm.com

media.ktm.com

KTM SPORTMOTORCYCLE GMBH

Paolo Carrubba // Head of Media and Public Relations // Tel.: +43 7742 6000 // Mobile: +39 347 9718769 // Email: paolo.carrubba@ktm.com // www.ktm.com

The KTM logo is displayed in a bold, black, italicized font on an orange square background.