

RECALL OF KTM 50 SX MODELS OF MODEL YEAR 2019: CHECK FITTING OF CARBURETOR COVER

Valid for all markets

KTM recalls KTM 50 SX models of model year 2019 to the workshops of authorized KTM dealers in order to check the fitting of the carburetor cover.

The carburetor covers may have been assembled incorrectly during production. As the cover is also working as carburetor slide stop, this may cause the slide to get stuck. The correct fitting of the carburetor cover must therefore be checked on affected vehicles.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized [KTM dealer](#) to arrange an appointment. In addition, customers can check online in the "[Service](#)" area on the KTM website if their motorcycle is affected by the recall.

The check of the fitting of the carburetor cover takes about 15 minutes and can be carried out by authorized KTM dealers only. This check is a free-of-charge service for customers performed under warranty.

KTM SPORTMOTORCYCLE GMBH

Stallhofnerstraße 3 // 5230 Mattighofen, Austria // P: +43 7742 / 60 00 // F: +43 7742 / 60 00-202 // www.ktm.com
EUR Bank Account: Deutsche Bank Wien // IBAN: AT52 1910 0000 3801 8001 // BIC: DEUTATWW
USD Bank Account: Deutsche Bank Wien // IBAN: AT87 1910 0000 3801 8050 // BIC: DEUTATWW
EUR Bank Account: Oberbank Mattighofen // IBAN: AT52 1504 1005 3111 8396 // BIC: OBKLAT2L
USD Bank Account: Oberbank Mattighofen // IBAN: AT76 1504 1002 1870 1431 // BIC: OBKLAT2L
UID-NR.: ATU 636 409 56 // FN: 295902 a // Ried im Innkreis

The KTM logo is displayed in a bold, black, italicized font against a solid orange square background.