

KTM RECALLS OFFROAD TWO-STROKE MOTORCYCLES OF THE MODEL YEAR 2013 TO EXCHANGE THROTTLE BY AUTHORIZED DEALERS!

The recall involves an improperly produced upper throttle housing half by the supplier. It is possible that the inner throttle cable could be pinched between the throttle wheel and the upper half of the throttle case.

There have been no incidents or accidents reported to KTM due to this issue.

The supplier as already remedied the deficiencies. KTM contacted all customers, in writing, who have already taken delivery of motorcycles affected by this recall. In addition, there is also the opportunity to check online if the motorcycle in question is affected by the recall action.

The recall information is available in the "Service" area of www.ktm.com and can be seen by entering the complete (17 digit) chassis number and the motorcycle's delivery certificate number.

The replacement of the upper half of the throttle case is to be exclusively performed by a specially trained, authorized KTM dealer. The repair takes about 10 minutes and is naturally guaranteed and free of charge.

The models which are involved in this recall are:
125 EXC, 125 EXC SIX DAYS, 125 SX, 150 SX, 150 XC, 200 EXC, 200 XC-W, 250 EXC, 250 EXC SIX DAYS, 250 SX, 250 XC, 250 XC-W, 300 EXC, 300 EXC SIX DAYS, 300 XC, 300 XC-W, 85 SX 17/14, 85 SX 19/16, 85 SXS 17/14.

