

RECALL OF ALL LC4 MODELS OF THE MODEL YEARS 2018 – 2020: INSPECTION / REPLACEMENT OF CLUTCH SLAVE CYLINDER

Valid for all markets

KTM recalls all LC4 models of the model years 2018 – 2020 to the workshops of authorized KTM dealers in order to inspect/replace the clutch slave cylinder.

Damage to the seal caused by deviations in assembly may impair the function of the clutch slave cylinder. All components of the version with a bellow gasket must therefore be replaced with the new version without a bellow gasket.

Customers to whom the affected motorcycles have already been delivered are informed by a personal letter and are asked to immediately contact an authorized KTM dealer to arrange an appointment for inspection/replacement.

The inspection/replacement can be carried out by authorized KTM dealers only. This inspection/replacement of the clutch slave cylinder is a free-of-charge service for customers performed under warranty.

KTM SPORTMOTORCYCLE GMBH

Stallhofnerstraße 3 // 5230 Mattighofen, Austria // P: +43 7742 / 60 00 // www.ktm.com
EUR Bank Account: Deutsche Bank Wien // IBAN: AT52 1910 0000 3801 8001 // BIC: DEUTATWW
USD Bank Account: Deutsche Bank Wien // IBAN: AT87 1910 0000 3801 8050 // BIC: DEUTATWW
EUR Bank Account: Oberbank Mattighofen // IBAN: AT52 1504 1005 3111 8396 // BIC: OBKLAT2L
USD Bank Account: Oberbank Mattighofen // IBAN: AT76 1504 1002 1870 1431 // BIC: OBKLAT2L
UID-NR.: ATU 636 409 56 // FN: 295902 a // Ried im Innkreis

