

RECALL OF KTM 125 & 150 SX EU AND 125 XC US MODELS OF MODEL YEAR 2022: REPLACING OF CDI CONTROL UNIT - NEW ZEALAND

KTM recalls KTM 125 & 150 SX EU and 125 XC US models of model year 2022 to the workshops of authorized KTM dealers in order to replace the CDI control unit.

To ensure the durability of the cranktrain, KTM is ordering a replacement of the CDI control unit on the above-mentioned vehicles. This replacement applies only to vehicles MY 2022.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized KTM dealer to arrange an appointment for replacement. In addition, customers can check online in the "Service" area on the KTM website if their motorcycle is affected by the recall.

The replacement of the CDI control unit can be carried out by authorized KTM dealers only. This replacement is a free-of-charge service for customers performed under warranty.

Important New Zealand market Safety Recall information:

Information for consumers and official safety recall information in relation to this product is available via the following link: <https://www.vehiclerecallsafety.nzta.govt.nz/>

Using the search function enter: KTM 125, 150 Model year 2022

Information on authorised **KTM** dealers can be found by using the dealer search function at: <https://www.ktm.com/en-nz/find-a-dealer.html>