

+++CONCERNS ALL MARKETS+++

## Recall Issued for the KTM ATV Models 450/525 XC and 450/505 SX

KTM is recalling the ATV models 450/525 XC from the 2008 and 2009 model years, as well as the 2009 model of the 450/505 SX, in order to replace the rear brake calliper support and the hand brake cylinder's piston return spring in officially authorised workshops.

A defect can develop in the rear brake calliper support of the 2008 and 2009 models of the 450/525 XC ATV and in the 2009 model of the 450/505 SX. Problems with the hand brake cylinder's piston return spring can also develop. It is essential to replace the affected parts immediately, in order to ensure the complete functional capability and reliability of the braking system, as well as the satisfaction and safety of our customers.

Buyers of the above-mentioned ATV models are therefore requested to contact an official KTM-authorized repair shop. The replacement of the rear brake calliper support and the piston return spring of the hand brake cylinder are naturally free of charge and can be accomplished in one short visit to a repair shop.

All owners of the models in question will personally receive written notices from KTM. It is also possible to verify whether a vehicle is affected by the recall online, at: [www.ktm.com](http://www.ktm.com)

- in the "Service" section
- Enter the chassis number
- Enter the delivery certificate number

[www.ktm.com](http://www.ktm.com)



### FOR FURTHER INFORMATION

KTM-Sportmotorcycle AG  
Thomas Kuttruf  
Public Relations Manager  
Tel.: +43 7742 6000  
Mobil: +43 664 81 62 490  
Fax: +43 7742 6000 – 5866  
e-Mail: [thomas.kuttruf@ktm.at](mailto:thomas.kuttruf@ktm.at)

Press information, 31.03.2009