

RECALL OF KTM OFFROAD MODELS

Valid for US and Canada markets

KTM recalls SX and FREERIDE bikes of different model years in order to be checked at authorized KTM Dealers.

Deviations in the manufacturing process of the molded fuel hoses of the motorcycles 250, 350, 450 SX-F MY2016 as well as 250 and 450 SX-F Factory Edition MY2015 can cause problems including uncontrolled fuel leakage at the bends or at the ends.

Market monitoring has shown that there can be problems with the tank breather in individual cases on FREERIDE 350 MY2012-2016 and FREERIDE 250 R MY2014-2016 models. Fuel may escape in extreme riding situations.

In extreme cases, the leaked fuel may cause damage or even a fire in the three cases referred to. In a limited number of cases, problems with the FREERIDE models have been reported; beyond this, no more damage of this type is known in the market.

All owners of affected and already delivered vehicles will be informed in writing by KTM. More information or the information whether the respective motorcycle is affected by the recall can be gathered at the [KTM Dealer](#).

The above-mentioned reviews can only be implemented by an authorized and qualified KTM Dealer. This guaranteeing is free of charge.

www.ktm.com

www.ktmimages.com



KTM 250 SX-F



KTM FREERIDE 250 R

The KTM logo, consisting of the letters 'KTM' in a bold, italicized, black font, set against a white background.

KTM SPORTMOTORCYCLE GMBH

Thomas Kuttruf // PR-Manager // Tel.: +43 7742 6000 – 866 // Mobile: +43 664 81 62 490
Fax: +43 7742 6000 – 5866 // Email: thomas.kuttruf@ktm.at // www.ktm.com