

RECALL OF KTM 450 RALLY REPLICAS MODELS OF MODEL YEAR 2019: REPLACEMENT OF FUEL TANK

Valid for Australia, Austria, Belgium, Brazil, Czech Republic, France, Germany, Italy, Netherlands, Norway, Paraguay, Poland, Portugal, Slovakia, South Africa, Spain, Sweden, Switzerland, United Kingdom

KTM recalls KTM 450 RALLY REPLICAS models of model year 2019 to the workshops of authorized KTM dealers in order to replace the rear fuel tank.

Nonconformities occurred in the production process of the rear fuel tank. In the area of the fuel pump flange, there may be minimal fuel leakage at one of the fitting inserts under certain circumstances. Accordingly, the rear fuel tanks need to be replaced on the vehicles affected.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized [KTM dealer](#) to arrange an appointment. In addition, customers can check online in the "[Service](#)" area on the KTM website if their motorcycle is affected by the recall.

The replacement of the fuel tank takes about 75 minutes and can be carried out by authorized KTM dealers only. This check is a free-of-charge service for customers performed under warranty.

KTM SPORTMOTORCYCLE GMBH

Stallhofnerstraße 3 // 5230 Mattighofen, Austria // P: +43 7742 / 60 00 // F: +43 7742 / 60 00-202 // www.ktm.com
EUR Bank Account: Deutsche Bank Wien // IBAN: AT52 1910 0000 3801 8001 // BIC: DEUTATWW
USD Bank Account: Deutsche Bank Wien // IBAN: AT87 1910 0000 3801 8050 // BIC: DEUTATWW
EUR Bank Account: Oberbank Mattighofen // IBAN: AT52 1504 1005 3111 8396 // BIC: OBKLAT2L
USD Bank Account: Oberbank Mattighofen // IBAN: AT76 1504 1002 1870 1431 // BIC: OBKLAT2L
UID-NR.: ATU 636 409 56 // FN: 295902 a // Ried im Innkreis

The KTM logo is displayed in a bold, black, italicized font against a solid orange background.