

## RECALL OF KTM 300 EXC SIX DAYS & KTM 450 XC-F MODELS OF MODEL YEAR 2023: INSPECTION / REPLACEMENT OF CLUTCH SLAVE CYLINDER

## Valid for all markets

KTM recalls KTM 300 EXC SIX DAYS & KTM 450 XC-F models of model year 2023 to the workshops of authorized KTM dealers in order to inspect/replace the clutch slave cylinder.

Deviations on an assembly line of our supplier may have caused damage to the seal of the clutch slave cylinder. This may impair its function. Consequently, the clutch slave cylinders on all affected vehicles must be checked and replaced if necessary.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized KTM dealer to arrange an appointment for inspection/replacement. In addition, customers can check online in the "Service" area on the KTM website if their motorcycle is affected by the recall.

The inspection/replacement of the clutch slave cylinder can be carried out by authorized KTM dealers only. This inspection/replacement is a free-of-charge service for customers performed under warranty.



