

## RECALL OF KTM SX MODELS OF MODEL YEAR 2016

## All markets

KTM recalls Motocross bikes of the latest model year 2016 to the workshops of authorized KTM dealers in order to review and replace the front wheel spokes.

During routine testing in ongoing production, KTM discovered that due to variations in the spoke manufacturing process, some spokes on the front wheels of 125, 150, 250 SX MY2016 and 250, 350, 450 SX-F MY2016 models may exhibit quality deviations.

Depending on where they are fitted in the wheel, care and spoke tension, it is possible that individual spokes may break while riding. This can overload the remaining intact spokes and consequently break them.

Customers of affected and already distributed motorcycles are informed by a personal letter and are asked to immediately contact an authorized <u>KTM dealer</u> to arrange an appointment. In addition, customers can check online in the "<u>Service</u>" area on the KTM website if their motorcycle is affected by the recall.

The review or the replacement of the front wheel spokes or the affected front wheels can be carried out by authorized KTM dealers only. This check is a guarantees that is completely free of charge.

www.ktm.com



## **KTM SPORTMOTORCYCLE GMBH**