

RECALL OF KTM 790 ADVENTURE & KTM 790 ADVENTURE R MODELS OF MODEL YEAR 2019 and 2020: REPLACEMENT OF REAR WHEEL BRAKE

Valid for all markets

KTM is recalling KTM 790 ADVENTURE & KTM 790 ADVENTURE R models of model year 2019 and 2020 to workshops of authorized KTM dealers in order to check & replace the rear wheel brake.

Due to a material nonconformity in the brake line, the rear brake system may fail under extreme conditions. Therefore, KTM is ordering the replacement of the brake line that leads from the rear brake caliper to the ABS modulator.

Customers to whom the affected motorcycles have already been delivered are being personally informed by letter and are asked to immediately contact an authorized [KTM dealer](#) to arrange an appointment. In addition, customers can check online in the "[Service](#)" area on the KTM website if their motorcycle is affected by the recall.

The revision of the rear wheel brake takes approximately 85 minutes and can only be carried out by an authorized KTM dealer. This work is free as it is covered by the guarantee.

KTM SPORTMOTORCYCLE GMBH

Stallhofnerstraße 3 // 5230 Mattighofen, Austria // P: +43 7742 / 60 00 // F: +43 7742 / 60 00-202 // www.ktm.com
EUR Bank Account: Deutsche Bank Wien // IBAN: AT52 1910 0000 3801 8001 // BIC: DEUTATWW
USD Bank Account: Deutsche Bank Wien // IBAN: AT87 1910 0000 3801 8050 // BIC: DEUTATWW
EUR Bank Account: Oberbank Mattighofen // IBAN: AT52 1504 1005 3111 8396 // BIC: OBKLAT2L
USD Bank Account: Oberbank Mattighofen // IBAN: AT76 1504 1002 1870 1431 // BIC: OBKLAT2L
UID-NR.: ATU 636 409 56 // FN: 295902 a // Ried im Innkreis

